

File

*FH 1322
"Proposals"*

MAR 21 1967

STATINTL

TO:

STATINTL

SUBJECT: ECP 1940-31, Contract AF33(657)-12846

Dear Chuck,

Subject ECP is technically approved by
the SPO. Request you provide formal authority for
 to proceed with this change.

Regards,

Carl
Carl

Atch

a/s

STATINTL

Copies:



STATINTL

EMR	Approved For Release	2002/06/14 : CIA-RDP72B00464R000400100007-4 ENGINEERING STUDY	<input type="checkbox"/>	EMR #	1940-31					
DATE	14 March 1967	AFFECTS:	EMR							
NAME OF MAJOR COMPONENT EMR System Assy. 321152-3		PART OR LOWEST SUBASSEMBLY Ground Straps (3) Stud	PART NO. 332142-1,2,3 325059-3		MODEL OR TYPE					
TITLE OF PROPOSAL: GROUND STRAP & GROUND STRAP FASTENER CHANGE										
NATURE OF PROPOSAL: The cad plated ground strap stud (325059-3) will be replaced by a stainless steel stud (325059-10). The lugs on the ground straps will be changed to eliminate the PVC, insulation band. The Stud, Ground Straps, Structure & Cover Assy, Right & Left and the overall EMR Assembly will be reidentified.										
REASON FOR PROPOSAL: To eliminate the use of cad plating and PVC in the proximity of the vehicle.										
ES	ESTIMATED COST AND TIME INVOLVED: ADDITIONAL FUNDING REQUIRED:									
CP	ESTIMATED COST FOR KITS OR PARTS: ADDITIONAL FUNDING REQUIRED:									
ITEMS AFFECTED BY PROPOSAL: D3, D4, D5, D8 EMRs will require field retrofit. The twenty spare sets of ground straps will require retrofit.										
SAFETY	MISSION EFFECTIVENESS	PERFORMANCE	OPERATING PROCEDURE	INTER-CHANGEABILITY	WEIGHT OR WEIGHT AND BALANCE	TOOLS AND SUPPORT EQUIPMENT	MAINTENANCE PROCEDURE	SERVICE LIFE	FLIGHT MANUAL	MAINTENANCE MANUAL
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ESTIMATED MAN HOURS REQUIRED TO ACCOMPLISH CHANGE IN FIELD: 1 hour for installation of ground straps & studs.										
SOURCE OF PARTS FOR KIT:					AVAILABILITY _____ WEEKS AFTER APPROVAL 30 April 1967					
DISPOSITION OF SPARES AFFECTED: Scrap 120 332142-1, 120 332142-2, 80 332142-3 NTL ground straps and 2 325059-3 studs.										
INITIATED BY:					APPROVED:					